Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

GY1001 MOBIL OIL S/S 17-F39 NY UST U003065854
East 1 NEPTUNE AVENUE NY Spills N/A

> 1 BROOKLYN, NY 11235

1.313 mi.

6935 ft. Site 1 of 13 in cluster GY

 Relative:
 UST:

 Higher
 Name:
 MOBIL OIL S/S 17-F39

 Actual:
 Address:
 1 NEPTUNE AVENUE

 6 ft.
 City,State,Zip:
 BROOKLYN, NY 11235

Id/Status: 2-157384 / Unregulated/Closed

Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A

UTM X: 588493.79283
UTM Y: 4492985.94474
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 5207 Affiliation Type: Facility Owner

Company Name: MOBIL OIL CORPORATION

Contact Type: Not reported Contact Name: Not reported

Address1: 3225 GALLOWS ROAD

 Address2:
 Not reported

 City:
 FAIRFAX

 State:
 VA

 Zip Code:
 22037

 Country Code:
 001

Phone: (703) 849-6252
EMail: Not reported
Fax Number: Not reported
Modified By: JPCUMMIN
Date Last Modified: 2010-12-13

Site Id: 5207
Affiliation Type: Mail Contact

Company Name: MOBIL OIL CORPORATION, NDE ENVIRONMENTAL

Contact Type: Not reported
Contact Name: NORMA HILL
Address1: PO BOX 142667
Address2: Not reported
City: AUSTIN
State: TX

 Zip Code:
 78714-2667

 Country Code:
 001

Phone: (800) 800-4633
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 5207

Affiliation Type: Facility Operator
Company Name: MOBIL OIL S/S 17-F39

Contact Type: Not reported
Contact Name: U BENEFANTE
Address1: Not reported

Direction Distance Elevation

nce EDR ID Number tion Site Database(s) EPA ID Number

Address2: Not reported City: Not reported State: NN

Zip Code: Not reported Country Code: 001

Phone: (718) 934-3247
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 5207

Affiliation Type: Emergency Contact

Company Name: MOBIL OIL CORPORATION

Contact Type: Not reported

Contact Name: ENVIRONMENTAL HELP DESK

Address1: Not reported Address2: Not reported City: Not reported State: NN Zip Code: Not reported

Country Code: 999

Phone: (800) 662-4567
EMail: Not reported
Fax Number: Not reported
Modified By: BKFALVEY
Date Last Modified: 2006-10-03

Tank Info:

Tank Number: 001 Tank ID: 29943

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 550
Install Date: 12/01/1973
Date Tank Closed: 10/01/1986
Registered: True
Tank Location: Underground

Tank Type: Steel/carbon steel
Material Code: 0009

Common Name of Substance: Gasoline

Tightness Test Method: NN

Date Test: Not reported Next Test Date: Not reported Pipe Model: Not reported Modified By: TRANSLAT Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None H00 - Tank Leak Detection - None

100 - Overfill - None

B00 - Tank External Protection - None C00 - Pipe Location - No Piping D02 - Pipe Type - Galvanized Steel F00 - Pipe External Protection - None G00 - Tank Secondary Containment - None Map ID MAP FINDINGS
Direction

Distance Elevation

ce EDR ID Number on Site Database(s) EPA ID Number

J02 - Dispenser - Suction Dispenser

 Tank Number:
 002

 Tank ID:
 29944

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 550
Install Date: 12/01/1973
Date Tank Closed: 10/01/1986
Registered: True
Tank Location: Underground

Tank Location: Underground
Tank Type: Steel/carbon steel

Material Code: 0009 Common Name of Substance: Gasoline

Tightness Test Method: NN

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None C00 - Pipe Location - No Piping D02 - Pipe Type - Galvanized Steel F00 - Pipe External Protection - None A00 - Tank Internal Protection - None H00 - Tank Leak Detection - None

100 - Overfill - None

G00 - Tank Secondary Containment - None J02 - Dispenser - Suction Dispenser

 Tank Number:
 003

 Tank ID:
 29945

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 550
Install Date: 12/01/1973
Date Tank Closed: 10/01/1986
Registered: True

Tank Location: Underground
Tank Type: Steel/carbon steel

Material Code: 0009 Common Name of Substance: Gasoline

Tightness Test Method: NN

Date Test: Not reported Next Test Date: Not reported Pipe Model: Not reported Modified By: TRANSLAT Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None C00 - Pipe Location - No Piping D02 - Pipe Type - Galvanized Steel F00 - Pipe External Protection - None

Direction Distance Elevation

Site EDR ID Number

EDR ID Number

EPA ID Number

A00 - Tank Internal Protection - None H00 - Tank Leak Detection - None

100 - Overfill - None

G00 - Tank Secondary Containment - None J02 - Dispenser - Suction Dispenser

Tank Number: 004
Tank ID: 29946

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 550
Install Date: 12/01/1973
Date Tank Closed: 10/01/1986
Registered: True

Tank Location: Underground Tank Type: Steel/carbon steel

Material Code: 0009

Common Name of Substance: Gasoline

Tightness Test Method: NN

Date Test:
Not reported
Next Test Date:
Not reported
Pipe Model:
Modified By:
TRANSLAT
Last Modified:

Not reported
Not reported
Od/14/2017

Equipment Records:

B00 - Tank External Protection - None C00 - Pipe Location - No Piping D02 - Pipe Type - Galvanized Steel F00 - Pipe External Protection - None H00 - Tank Leak Detection - None

100 - Overfill - None

A00 - Tank Internal Protection - None G00 - Tank Secondary Containment - None J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 29947

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 550
Install Date: 12/01/1973
Date Tank Closed: 10/01/1986
Registered: True

Tank Location: Underground Tank Type: Steel/carbon steel

Material Code: 0009 Common Name of Substance: Gasoline

Tightness Test Method: NN

Date Test: Not reported Next Test Date: Not reported Pipe Model: Not reported Modified By: TRANSLAT Last Modified: 04/14/2017

Equipment Records:

Direction Distance Elevation

Site EDR ID Number

Database(s) EPA ID Number

B00 - Tank External Protection - None C00 - Pipe Location - No Piping D02 - Pipe Type - Galvanized Steel F00 - Pipe External Protection - None A00 - Tank Internal Protection - None H00 - Tank Leak Detection - None

100 - Overfill - None

G00 - Tank Secondary Containment - None J02 - Dispenser - Suction Dispenser

 Tank Number:
 006

 Tank ID:
 29948

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 550

Install Date: 12/01/1973
Date Tank Closed: 10/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN

Date Test: Not reported Next Test Date: Not reported Pipe Model: Not reported Modified By: TRANSLAT Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None C00 - Pipe Location - No Piping D02 - Pipe Type - Galvanized Steel F00 - Pipe External Protection - None H00 - Tank Leak Detection - None

100 - Overfill - None

A00 - Tank Internal Protection - None G00 - Tank Secondary Containment - None J02 - Dispenser - Suction Dispenser

Tank Number: 007 Tank ID: 29949

Tank Status: Closed - Removed Material Name: Closed - Removed

 Capacity Gallons:
 550

 Install Date:
 12/01/1973

 Date Tank Closed:
 10/01/1986

 Registered:
 True

Tank Location: Underground
Tank Type: Steel/carbon steel

Material Code: 0009 Common Name of Substance: Gasoline

Tightness Test Method: NN

Date Test: Not reported Next Test Date: Not reported Pipe Model: Not reported

Direction Distance Elevation

Site EDR ID Number

EDR ID Number

EPA ID Number

Modified By: TRANSLAT Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None

100 - Overfill - None

B00 - Tank External Protection - None C00 - Pipe Location - No Piping D02 - Pipe Type - Galvanized Steel F00 - Pipe External Protection - None A00 - Tank Internal Protection - None G00 - Tank Secondary Containment - None J02 - Dispenser - Suction Dispenser

 Tank Number:
 008

 Tank ID:
 29950

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 550

Install Date: 12/01/1973
Date Tank Closed: 10/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN

Date Test: Not reported Next Test Date: Not reported Pipe Model: Not reported Modified By: TRANSLAT Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None H00 - Tank Leak Detection - None

100 - Overfill - None

B00 - Tank External Protection - None C00 - Pipe Location - No Piping D02 - Pipe Type - Galvanized Steel F00 - Pipe External Protection - None G00 - Tank Secondary Containment - None J02 - Dispenser - Suction Dispenser

 Tank Number:
 009

 Tank ID:
 29951

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 550
Install Date: 12/01/1973
Date Tank Closed: 10/01/1986
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

Material Code: 0009
Common Name of Substance: Gasoline

Direction Distance Elevation

nce EDR ID Number ation Site Database(s) EPA ID Number

Tightness Test Method: NN

Date Test: Not reported Next Test Date: Not reported Pipe Model: Not reported Modified By: TRANSLAT Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None

100 - Overfill - None

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

J02 - Dispenser - Suction Dispenser

Tank Number: 010 Tank ID: 29952

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 550
Install Date: 12/01/1973
Date Tank Closed: 10/01/1986
Registered: True

Tank Location: Underground
Tank Type: Steel/carbon steel

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN

Date Test: Not reported Next Test Date: Not reported Pipe Model: Not reported Modified By: TRANSLAT Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None H00 - Tank Leak Detection - None

100 - Overfill - None

B00 - Tank External Protection - None C00 - Pipe Location - No Piping D02 - Pipe Type - Galvanized Steel F00 - Pipe External Protection - None G00 - Tank Secondary Containment - None J02 - Dispenser - Suction Dispenser

Tank Number: 011 Tank ID: 29953

Tank Status: Closed - Removed Material Name: Closed - Removed

Capacity Gallons: 275
Install Date: 12/01/1974
Date Tank Closed: 10/01/1986
Registered: True
Tank Location: Underground

Map ID MAP FINDINGS
Direction

Distance Elevation

on Site Database(s) EPA ID Number

Tank Type: Steel/carbon steel

Material Code: 9999 Common Name of Substance: Other

Tightness Test Method: NN

Date Test:
Not reported
Next Test Date:
Not reported
Pipe Model:
Modified By:
Last Modified:
Not reported
TRANSLAT
Ud/14/2017

Equipment Records:

H00 - Tank Leak Detection - None

100 - Overfill - None

B00 - Tank External Protection - None C00 - Pipe Location - No Piping D02 - Pipe Type - Galvanized Steel F00 - Pipe External Protection - None A00 - Tank Internal Protection - None G00 - Tank Secondary Containment - None

SPILLS:

Name: MOBIL S/S

Address: 1 NEPTUNE AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8604897 / 1986-10-31

 Facility ID:
 8604897

 Facility Type:
 ER

 DER Facility ID:
 99510

 Site ID:
 114060

 DEC Region:
 2

Spill Cause: Equipment Failure

C3 Spill Class: SWIS: 2401 Spill Date: 1986-10-29 Investigator: **SIGONA** Referred To: Not reported Reported to Dept: 1986-10-31 CID: Not reported Water Affected: Not reported

Spill Source: Gasoline Station or other PBS Facility

Spill Notifier: Other
Cleanup Ceased: 1986-10-31
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered in Computer: 1987-03-31

Date Entered In Computer: 1987-03-31 Spill Record Last Update: 2003-05-27

Spiller Name: PAUL BETTENCOURT
Spiller Company: EXXONMOBIL

Spiller Address: 3225 GALLOWS ROAD Spiller Company: 001

Contact Name: Not reported DEC Memo: ""

Remarks: "SUSPECTED TANK LEAK."

All Materials:

Site ID: 114060

EDR ID Number

Direction Distance Elevation

EDR ID Number
Site Database(s) EPA ID Number

Operable Unit ID: 902100 Operable Unit: 01 Material ID: 474123 Material Code: 0009 Material Name: gasoline Case No.: Not reported Material FA: Petroleum .00 Quantity:

Units: G
Recovered: .00

Oxygenate: Not reported

Site ID: 114060 Operable Unit ID: 902100 Operable Unit: 01 Material ID: 474124 Material Code: 1264A Material Name: mobil oil Case No.: Not reported Material FA: Petroleum .00 Quantity: G Units: .00 Recovered:

Oxygenate: Not reported

Name: MOBIL S/S

Address: 1 NEPTUNE AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8604923 / 2001-01-01

 Facility ID:
 8604923

 Facility Type:
 ER

 DER Facility ID:
 99510

 Site ID:
 114061

DEC Region: 2

Spill Cause: Housekeeping

Spill Class: В3 SWIS: 2401 1986-11-03 Spill Date: Investigator: SIGONA Referred To: Not reported Reported to Dept: 1986-11-03 CID: Not reported Water Affected: NONE

Spill Source: Gasoline Station or other PBS Facility

Spill Notifier:
Cleanup Ceased:
Cleanup Meets Std:
Last Inspection:
Recommended Penalty:
UST Trust:
Remediation Phase:
Local Agency
Not reported
False
False
0

Date Entered In Computer: 1986-11-05
Spill Record Last Update: 2003-05-27
Spiller Name: Not reported
Spiller Company: EXXONMOBIL

Spiller Address: 3225 GALLOWS ROAD

Spiller Company: 001
Contact Name: Not reported

Map ID MAP FINDINGS
Direction

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

DEC Memo:

Remarks: "GASOLINE & VAPORS IN UNDERGROUND UTILITIES, ABANDONED MOBIL STATION

IN THE AREA"

All Materials:

114061 Site ID: Operable Unit ID: 901893 Operable Unit: 01 Material ID: 474148 Material Code: 0009 Material Name: gasoline Case No.: Not reported Material FA: Petroleum Quantity: .00 Units: G Recovered: .00

Oxygenate: Not reported